DEPARTMENT OF TRANSPORTATION FEDERAL AVIATION ADMINISTRATION MERRILL AIRPORT TRAFFIC CONTROL TOWER 1950 EAST 5TH AVENUE ANCHORAGE, ALASKA 99501

ISSUED: November 14, 2002

EFFECTIVE: November 15, 2002

MERRILL ATCT LETTER TO AIRMEN NO. 02-01

SUBJECT: AREAS OF NON-VISIBILITY

CANCELLATION: November 2, 2004

Due to the obstruction of vision created by trees, certain aircraft may not be visible to controllers in the airport traffic control tower in the following areas:

Portions of Taxiway Charlie between Taxiways November and Papa.

Portions of Runway 15-33 between Taxiways November and Papa.

Pilots are advised to use caution in these areas.

Linda J. Coulure

Air Traffic Manager, Merrill ATCT